



※Notice of Autonomous Inspection of Campus Buildings Following the Earthquake 20240403
(Wednesday)※

DATE	2024/04/03
TIME	07:58 a.m.
PLACE	Due to the earthquake of magnitude 7.2 on the Richter scale that occurred near the coast of Hualien County.
Explanation	<p>1. In order to ensure the safety of our faculty, staff, and students, our department has dispatched personnel to conduct autonomous inspections of campus buildings:</p> <ul style="list-style-type: none">(1) Inspection of various high-voltage substations on campus to check for any abnormalities.(2) Patrol of campus public water supply pipelines to inspect for any abnormalities or damage.(3) After confirming the safety of all assumed construction projects or temporary structures on campus, subsequent construction operations will be carried out. <p>2. To ensure the safety of our faculty, staff, and students, we kindly request all building management committee members and administrators to conduct autonomous inspections of relevant safety facilities and equipment within the buildings. In case of any damage, please fill out the attached "National Chung Hsing University Campus Building Damage Survey Form" and attach photos of the damage. Please submit the form by 5:00 PM on 2024/04/12(Friday), to maintenance@nchu.edu.tw.</p>
Office	General Affairs Office Division of Construction and Maintenance
Contact Us	04-22840276-279

2024/04/03